

**LUCAS**

## Color codes used in wiring harnesses

Wire Color		Function
Blue/White		High Beam
Blue/Red		Low Beam
Blue		To headlamp dip switch
Red		Side lights
Green/White		RH Turn signals
Green/Red		LH Turn signals
Green/Purple		Brake lights
Black		Ground
Brown		Most non fused +ve
Purple		Most fused constant +ve
White		Non fused, ign controlled
Green		Fused, ignition controlled
Light Green		Stabilized 5 /10v to gauges
Red		Gauge lights not on dimmer
Red/White		Gauge lights on dimmer
White/Slate		Electric tacho (from coil)
Purple/Black		Horn switch
Green/Blue		Temp Gauge (from sender)
Green/Black		Fuel Gauge (from sender)
Green/Orange		Fuel warning light

*First color is the wire - second is the stripe*